

09/627,381

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	325360	conductor or wiring	USPAT; US-PGP UB	2002/06/02 14:17
2	BRS	L2	3238	overetch or overetching	USPAT; US-PGP UB	2002/06/02 14:17
3	BRS	L3	240	1 same 2	USPAT; US-PGP UB	2002/06/02 14:17
4	BRS	L4	102	3 same (dielectric or insulator or insulating)	USPAT; US-PGP UB	2002/06/02 14:31
5	BRS	L5	1	"5960311".PN.	USPAT	2002/06/02 14:20
6	BRS	L6	1	"5789314".PN.	USPAT	2002/06/02 14:20
7	BRS	L7	1	"5716888".PN.	USPAT	2002/06/02 14:20
8	BRS	L8	1	"5668398".PN.	USPAT	2002/06/02 14:21
9	BRS	L9	1	"5641712".PN.	USPAT	2002/06/02 14:21
10	BRS	L10	1	"5641712".PN.	USPAT	2002/06/02 14:21
11	BRS	L11	1	"5559055".PN.	USPAT	2002/06/02 14:21
12	BRS	L12	1	"5461003".PN.	USPAT	2002/06/02 14:21
13	BRS	L13	1	"5407860".PN.	USPAT	2002/06/02 14:22
14	BRS	L14	1	"5310700".PN.	USPAT	2002/06/02 14:22
15	BRS	L15	1	"5310700".PN.	USPAT	2002/06/02 14:23
16	BRS	L16	1	"5278103".PN.	USPAT	2002/06/02 14:23
17	BRS	L17	1	"5217926".PN.	USPAT	2002/06/02 14:23
18	BRS	L18	1	"4986878".PN.	USPAT	2002/06/02 14:23
19	BRS	L19	1	"4801560".PN.	USPAT	2002/06/02 14:24

	Comments	Error Definition	Errors
1			0
2			0
3			0
4			0
5			0
6			0
7			0
8			0
9			0
10			0
11			0
12			0
13			0
14			0
15			0
16			0
17			0
18			0
19			0

	Type	L #	Hits	Search Text	DBs	Time Stamp
20	IS&R	L20	4163	((438/622) or (438/623) or (438/624) or (438/631)).CCLS.	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM_TD B	2002/06/02 14:33

	Comments	Error Definition	Errors
20			0